



Project: Oak Ridge Residence

Address: 14 Oak Ridge Lane

Project #: WL-2026-0847

Date of loss: July 12, 2026

Insurer: Sample Mutual

Claim #: CLM-2026-0847



First Floor — Sample Residence




Photo Log

Living Room

Field notes

Living Room

Category 2 water — baseboards swollen; flooring cupped at south wall.



Photo 1

Living Room — wet flooring and baseboard damage

Photo Log

Living — Window

Field notes

Living — Window

North window wall — moisture staining on drywall below sill.



Photo 2

Living Room — window wall moisture stain

Photo Log

Living — SE

Field notes

Living — SE

Air mover placed at SE corner — directed at wet wall cavity.



Photo 3

Living Room — drying equipment placement

Photo Log

Kitchen

Field notes

Kitchen

Kitchen — cabinet toe-kicks wet; meter reading elevated at sink base.



Photo 4

Kitchen — wet cabinets and sink base

Photo Log

Kitchen — Cook

Field notes

Kitchen — Cook

Cooktop wall — no fire damage; water migrated from hall.



Photo 5

Kitchen — cook area after water migration

Photo Log

Dining

Field notes

Dining

Dining — carpet pad saturated; dehumidifier staged in corner.



Photo 6

Dining — saturated flooring and dehu placement

Photo Log

Dining — East

Field notes

Dining — East

East wall — drywall removed to 2 ft; cavity drying in progress.



Photo 7

Dining — demo cut and cavity drying

Hall — West

Field notes

Hall — West

Hall west — source path from living; moisture map updated.



Photo 8

Hall — west corridor moisture path

Photo Log

Hall — East

Field notes

Hall — East

Hall east — containment zipper toward bedrooms.



Photo 9

Hall — east corridor containment

Photo Log

Bedroom 1

Field notes

Bedroom 1

Primary bedroom — contents packed out; flooring removed at perimeter.



Photo 10

Bedroom 1 — pack-out and perimeter demo

Photo Log

Bedroom 1 — NE

Field notes

Bedroom 1 — NE

Northeast corner — air mover on wet wall; daily readings logged.



Photo 11

Bedroom 1 — equipment and moisture readings

Bath

Field notes

Bath

Bath — vanity kick plate wet; possible secondary source checked.



Photo 12

Bath — vanity and wet kick plate

Closet

Field notes

Closet

Closet — contents removed; base plate moisture confirmed.



Photo 13

Closet — cleared for drying access

Bedroom 2

Field notes

Bedroom 2

Secondary bedroom — unaffected finishes; control readings taken.



Photo 14

Bedroom 2 — control area / unaffected finishes

Bedroom 2 — Window

Field notes

Bedroom 2 — Window

East window — no intrusion; used as dry baseline photo.



Photo 15

Bedroom 2 — dry baseline at window wall